### Proposed Emergency Regulation: Diesel Agriculture Pump Engines



March 17, 2005



#### **History**

- Adopted February 2004
- New engine requirements took effect January 2005
- New Engine PM Emission Standards (g/bhp-hr)
  - Industrial Application 0.01
  - Agricultural Application 0.15
  - Emergency Standby Application 0.15

#### **Complying Pump Engines Meeting 0.15 PM Standard Are Not Available in All Size Ranges**

- 50-100 hp very limited availability
- 101-175 hp not available in all sizes by all manufacturers
- Greater than 175 hpfully available



#### **Today's Proposed Action**

- Modify Stationary ATCM on emergency basis for 50-100 hp Stationary Ag pump engines
- Initiate expedited rule making
  - Establish permanent rule modification for 50-100 hp pump engines
  - Initiate effort to determine if changes are needed for 101-175 hp pump engines

#### **Ag Engine Inventory**

Size (hp)	# of Engines
50-100	200
101-175	2,000
176+	3.000



## **Estimated Demand for New Pump Engines over the Next Four Years**



Size (hp)	<b>Units/Yr</b>			
50-100	25			
101-175	250			
> 175	400			

#### Moyer Program Will Help Buy New Ag Engines

- Moyer programs expected to pay for 60 to 80% of the cost of a new engine
- Remaining 20 to 40% privately funded
- Over the past 5 years, Moyer programs have helped replace 2,200 ag engines

### **Availability of Ag Engines Meeting 0.15 PM Limit**

Size (hp)

50-100

101-175

# of Engines

7 of 52

37 of 70



## Pump Engines Available in the 50-100 hp Range

Mfc.	Α	В	С	D	E	
50- 69	2	0	0	*	0	
70-89	0	0	0	0	1	
90-100	1	2	*	0	1	
Total Complying/ Non complying	3/14	2/20	0/5	0/4	2/9	7/52

<sup>\*</sup> no engines in the hp range

## Pump Engines Available in the 101-175 hp Range

Mfc.	Α	В	С	D	E	
HP Range						
101-120	0	3	*	0	0	
121-140	1	7	0	0	0	
141-160	1	7	*	0	1	
161-175	4	14	0	1	0	
Total 6/20 29/37 0/2 1/7 1/4 37/70 Complying/ Non complying * no engines in the hp range						

# **Issues Caused by Lack of Availability of 0.15 Engines**

- Certain engines can not be replaced with a like model from the same manufacturer
- Approval of about 20 Moyer applications will be delayed or will need to be amended
- Delay in replacing older engines could eventually delay emissions reductions
- Some lower priced engines can not be used, not all brands are available in all sizes

### Issues Caused By Lack of Availability (cont.)

- Certain manufactures and their dealers will loose business to those with complying engines
- Non complying engines in inventory will have to be sold out of state
- Growers may not be able to obtain complying engines for the spring growing season

#### Recommendations

- Modify ATCM on emergency basis for 50 - 100 hp pump engines
- Return in May with amendments to ATCM for 50 - 100 hp category



#### Recommendations (cont.)

 Investigate the need for similar changes to ATCM for 101 - 175 hp category, and include in May rulemaking if appropriate

